

WVAW OPERATION LOG AS OF 18 JAN AT 1800

SAMPLE LOCATION COUNTY	TIME & DATE	SAMPLE NUMBER	RESULTS PPM/RECEIVED
WVAW	JAN 10 1230pm	1230	IN= 1.04 OUT= 1.21 IN= 3.35 OUT= 1..56
WVAW	JAN 10 155pm	1355	IN= 1.229 OUT= .906 IN= 1.19 OUT= 1.3
WVAW	JAN 10 4PM	1600	IN= 1.222 OUT=.865 IN=1.39 OUT=1.28
WVAW	JAN 10 555PM	1755	IN= 0.802 OUT= .777 IN=1.27 OUT= 1.28
WVAW	JAN 10 750PM	1950	IN= .785 OUT= .809 IN= .2.2 OUT= 2.4
WVAW	JAN 10 11PM	2300	IN= 1.7 OUT= .75
WVAW	JAN 11 1AM	O100	IN= 1.647 OUT= .628
WVAW	JAN 3AM	O300	IN= 1.081 OUT= .649 IN=1.05 OUT= 3.12
WVAW	JAN 11 5AM	O500	IN= 1.87 OUT= 1.01 IN=3.17 OUT= 1.47
WVAW	JAN 11 7AM	O700	IN= 1.3 OUT= 1.1 IN= .92 OUT=.78
WVAW	JAN 11 902AM	O902	IN= .7 OUT= .6 IN=.92 OUT= .78
WVAW	JAN 11 10AM	1000	IN= .488 OUT= .622
WVAW	JAN 11 1115AM	1115	IN= .28 OUT=.58
WVAW	JAN 11 1210PM	1210	IN= .21 OUT= .66
WVAW	JAN 11 110PM	1310	IN= .23 OUT=.76
WVAW	JAN 11 215PM	1415	IN= .8 OUT= .3
WVAW	JAN 11 4PM	1600	IN= .11 OUT=.53
WVAW	JAN 11 515PM	1715	IN=.12 OUT= .34
WVAW	JAN 11 6PM	1800	IN= 0.1 OUT= .5
WVAW	JAN 11 7PM	1900	IN= 0.029 OUT= .41
WVAW	JAN 11 8PM	2000	IN= ND OUT= .33
WVAW	JAN 11 10PM	2200	IN= .02 OUT= .18
WVAW	JAN 11 11PM	2300	IN= .014 OUT=.21
WVAW	JAN 11 1101PM	2301	IN= .04 OUT=.21
WVAW	JAN 12 12AM	2400	IN= .00 OUT= .09

WVAW	JAN 12 1AM	O100	IN=.1 OUT= .12
WVAW	JAN 12 2AM	O200	IN= ND OUT= .5
WVAW	JAN 12 3AM	O300	IN= ND OUT= .1
WVAW	JAN 12 4AM	O400	IN=ND OUT=.04
WVAW	JAN 12 5AM	O500	IN=ND OUT=.04
WVAW	JAN 12 5AM	O500	IN=ND OUT=.07
WVAW	JAN 12 6AM	O600	IN=ND OUT=ND
WVAW	JAN 12 4PM	1600	IN=0.33 OUT=0.69
WVAW	JAN 12 6PM	1800	IN=0.39 OUT=NO DATA REPORTED
WVAW	JAN 12 4PM	1600	IN=ND OUT=.0021
WVAW	JAN 12 6PM	1800	IN=ND OUT=0.0178
WVAW	JAN 12 8PM	2000	IN=0.021 OUT=0.0022
WVAW	JAN 12 10PM	2200 A	OUT= 0.03 OUT=.0.025
WVAW	JAN 13 0005	5	OUT=0.05 OUT=ND
WVAW	JAN 13 0210	210	IN=ND OUT=0.015PPM
WVAW	JAN 13 0405	405	IN=ND OUT=ND
WVAW	JAN 13 0600	600	IN=ND OUT=ND
WVAW	JAN 13 0600	600	IN=ND OUT=ND
WVAW	JAN 13 1000	1000	IN=ND OUT=ND
WVAW	JAN 13 1300	1300	IN=ND OUT=ND
WVAW	JAN 13 1000	1000	IN=ND OUT=ND
WVAW	JAN 13 1045	1045	IN=ND
WVAW	JAN 13 1004	1004	OUT=ND
WVAW	JAN 13 0600	600	OUT=ND
WVAW	JAN 13 1700	1700	IN=ND
WVAW	JAN 13 1500	1500	IN=ND OUT=ND
WVAW	JAN 13 2100	2100	IN=0.018
WVAW	JAN 13 2014	2014	IN=ND OUT=ND
WVAW	JAN 13 2200	2200	IN=0.00137 OUT=0.01059
WVAW	JAN 13 2100	2100	IN=0.00204 OUT=0.01078
WVAW	JAN 13 2016	2016	IN=ND OUT=0.01087
WVAW	JAN 13 1800	1800	IN=ND
WVAW	JAN 13 2014	2014	IN=ND OUT=ND
WVAW	JAN 13 2100	2100	IN=0.018 OUT=0.016

WV AW	JAN 13 2200	2200	IN=ND
WVAW	JAN 14 0200	200	IN=ND
WVAW	JAN 13 2200	2200	IN=ND
WVAW	JAN 13 0200	200	IN=ND
WVAW	JAN 14 0600	600	IN=ND OUT=ND
WV AW	JAN 14 1000	1000	IN=ND OUT=ND
WV AW	JAN 14 1021	1021	IN=ND OUT=ND
WV AW	JAN 14 1700	1700	IN=ND OUT=ND
WV AW	JAN 14 1900	1900	IN=ND OUT=ND
WV AW	JAN 14 1800	1800	IN=ND OUT=ND
WV AW	JAN 14 1900	1900	IN=ND OUT=ND
WV AW	JAN 14 2100	2100	IN=ND OUT=ND
WV AW	JAN 14 2100	2100	IN=ND OUT=ND
WV AW	JAN 14 1400	1400	IN=ND OUT=ND
WV AW	JAN 14 1621	1621	IN=ND OUT=ND
WV AW	JAN 14 2300	2300	IN=ND OUT=ND
WV AW	JAN 14 2000	2000	IN=ND OUT=ND
WV AW	JAN 14 2200	2200	IN=ND OUT=ND
WV AW	JAN 14 2300	2300	IN=ND OUT=ND
WV AW	JAN 14 2300	2300	IN=ND OUT=ND
WV AW	JAN 14 0800	800	IN=ND OUT=ND
WV AW	JAN 14 1200	1200	IN=ND OUT=ND
WV AW	JAN14 1400	1400	IN=ND OUT=ND
WV AW	JAN 14 1600	1600	IN=ND OUT=ND
WV AW	JAN 15 0100	100	IN=ND OUT=ND
WV AW	JAN 15 0100	100	IN=ND OUT=ND
WV AW	JAN 15 0000	0	IN=ND OUT=ND
WV AW	JAN 15 0200	0200	IN=ND OUT=ND
WV AW	JAN 15 0500	0500	IN=ND OUT=ND
WV AW	JAN 15 0300	0300	OUT=ND
WVAW	JAN 15 1300	1300	IN=ND OUT=ND
WVAW	JAN 15 1400	1400	IN=ND OUT=ND
WVAW	JAN 15 1500	1500	IN=ND OUT=ND
WVAW	JAN 15 1000	1000	IN=ND OUT=ND

*SP
*JP

WVAW	JAN 15 0425	425	IN=ND OUT=ND
WVAW	JAN 15 1200	1200	IN=ND OUT=ND
WVAW	JAN 15 0800	800	IN=ND OUT=ND
WVAW	JAN 15 1000	1000	IN=ND OUT=ND
WVAW	JAN 15 1500	1500	IN=ND OUT=ND
WVAW	JAN 15 1300	1300	IN=ND OUT=ND
WVAW	JAN 15 1400	1400	IN=ND OUT=ND
WVAW	JAN 15 1500	1500	IN=ND OUT=ND
WVAW	JAN 15 1300	1300	IN=ND OUT=ND
WVAW	JAN 15 1400	1400	IN=ND OUT=ND
WVAW	JAN 15 0400	400	IN=ND
WVAW	JAN 15 1758	1758	OUT=ND
WVAW	JAN 15 0600	600	IN=ND OUT=ND
WVAW	JAN 15 1500	1500	IN=ND OUT=ND
WVAW	JAN 15 1700	1700	IN=ND OUT=ND
WVAW	JAN 15 1600	1600	IN=ND OUT=ND
WVAW	JAN 15 1800	1800	IN=ND OUT=ND
WVAW	JAN 15 1900	1900	IN = ND
WVAW	JAN 15 1300	1300	IN=ND
WVAW	JAN 15 1900	1900	IN=ND OUT=ND
WVAW	JAN 15 2100	2100	IN=ND OUT=ND
WVAW	JAN 15 1700	1700	OUT=ND
WVAW	JAN 15 2200	2200	IN=ND OUT=ND
WVAW	JAN 15 2000	2000	IN=ND OUT=ND
WVAW	JAN 15 2100	2100	IN=ND OUT=ND
WVAW	JAN 14 2000	2000	IN=ND OUT=ND
WVAW	JAN 14 2200	2200	IN=ND OUT=ND
WVAW	JAN 15 2300	2300	IN=ND OUT=ND
WVAW	JAN 14 1800	1800	IN=ND OUT=ND
WVAW	JAN 14 2300	2300	IN=ND OUT=ND
WVAW	JAN 16 0000	0	IN=ND OUT=ND
WVAW	JAN 16 0100	100	IN=ND OUT=ND
WVAW	JAN 16 0100	100	IN=ND OUT=ND
WVAW	JAN 15 2000	2000	IN=ND OUT=ND

WVAW	JAN 15 2200	2200	IN=ND OUT=ND
WVAW	JAN 16 0300	300	IN=ND OUT=ND
WVAW	JAN 16 0000	0	IN=ND OUT=ND
WVAW	JAN 16 0300	300	IN=ND OUT=ND
WVAW	JAN 16 0200	200	IN=ND OUT=ND
WVAW	JAN 16 0700	700	IN=ND OUT=ND
WVAW	JAN 16 0400	400	IN=ND OUT=ND
WVAW	JAN 16 0500	500	IN=ND OUT=ND
WVAW	JAN 16 0500	500	IN=ND OUT=ND
WVAW	JAN 15 1600	1600	IN=ND OUT=ND
WVAW	JAN 15 1200	1200	IN=ND OUT=.00409
WVAW	JAN 15 1100	1100	IN=ND OUT=.00331
WVAW	JAN 15 1000	1000	IN=.0003 OUT=.00304
WVAW	JAN 16 0900	900	IN=ND OUT=ND
WVAW	JAN 16 0900	900	IN=ND OUT=ND
WVAW	JAN 16 0200	200	IN=ND OUT=ND
WVAW	JAN 16 0400	400	IN=ND OUT=ND
WVAW	JAN 16 1100	1100	IN=ND OUT=ND
WVAW	JAN 16 1000	1000	IN=ND OUT=ND
WVAW	JAN 16 0600	600	IN=ND OUT=ND
WVAW	JAN 16 0800	800	IN=ND OUT=ND
WVAW	JAN 16 1300	1300	IN=ND OUT=ND
WVAW	JAN 15 1600	1600	IN=ND OUT=ND
WVAW	JAN 15 1200	1200	IN=ND OUT=.00409
WVAW	JAN 15 1100	1100	IN=ND OUT=.00331
WVAW	JAN 15 1000	1000	IN=ND OUT=.00304
	JAN 15 1600	1600	IN=ND OUT=ND
	JAN 15 1000	1000	IN=ND OUT=ND
	JAN 15 1300	1300	IN=ND OUT=ND
	JAN 15 0800	800	IN=ND OUT=ND
	JAN 15 1800	1800	IN=ND OUT=ND
	JAN 15 1100	1100	IN=ND OUT=ND
	JAN 15 0900	900	IN=ND OUT=ND
	JAN 15 1200	1200	IN=ND OUT=ND

	JAN 15 1400	1400	IN=ND OUT=ND
	JAN 15 1400	1400	IN=ND OUT=ND
	JAN 15 1500	1500	IN=ND OUT=ND
	JAN 15 1600	1600	IN=ND OUT=ND
	JAN 15 1700	1700	IN=ND OUT=ND
	JAN 16 1900	1900	IN=ND OUT=ND
	JAN 16 1800	1800	IN=ND OUT=ND
	JAN 16 2100	2100	IN=ND OUT=ND
	JAN 16 2200	2200	IN=ND OUT=ND
	JAN 16 1800	1800	IN=ND OUT=ND
	JAN 16 1100	1100	IN=ND OUT=ND
	JAN 17 1200	1200	IN=ND OUT=ND
	JAN 17 0100	100	IN=ND OUT=ND
	JAN 16 2300	2300	IN=0.00000 OUT=ND
	JAN 17 0000	0	IN=0.00000 OUT=ND
	JAN 17 0100	100	IN=ND OUT=ND
	JAN 16 1100	1100	IN=ND OUT=ND
	JAN 16 1300	1300	IN=ND OUT=ND
	JAN 16 1400	1400	IN=ND OUT=ND
	JAN 16 1500	1500	IN=ND OUT=ND
	JAN 16 1600	1600	IN=ND OUT=ND
	JAN 16 1700	1700	IN=ND OUT=ND
	JAN 18 0600	600	IN=ND OUT=ND
	16 JAN 0500	500	IN=ND OUT=ND
	16 JAN 0900	900	IN=ND OUT=ND
	16 JAN 1200	1200	IN=ND OUT=ND
	16 JAN 1400	1400	IN=ND OUT=ND
	16 JAN 1600	1600	IN=ND OUT=ND
	16 JAN 1800	1800	IN=ND OUT=ND
	1/16/2014 2000	2000	IN=ND OUT=ND
	JAN 16 2100	2100	IN=ND OUT=ND
	JAN 16 2200	2200	IN=ND OUT=ND
	JAN 17 1716	1716	IN=ND OUT=ND